

Instruments and Data Acquisition

PMAC 2000

GRAPHIC USER INTERFACE (GUI)

An optional Graphic User Interface (GUI) is now available for linking PMAC 2000 to a PC via serial port. The GUI provides single screen calibration and setup of transducers, limits, and operational modes. It also provides an easy means to view and upload stored data into spreadsheets or text files, and allows the user a simple way of saving or retrieving data from disk.

